

Working at Height

Identified hazards:



Vehicles

Hazards?

Working

Passing

At risk: All staff and other persons in the work area.

Spillages



Keeping

Lighting



The calculated risk factor for this task/operation is 6 (Probability: 1 x Severity: 6)

This is classed as a LOW risk



Working at Height

Additional Measures:

Further Measures	Person Responsible	Date for Completion
Stepladders to be checked by employee at start of every day prior to use.	FM Technician	Ongoing
Before using equipment, ensure pre-use checks are performed.	FM Technician	Ongoing
Ensure read and comply with any workplace rules, manufacturer's instructions and method statements.		Ongoing
When signing in, inform reception of time expected to complete task by.	FM Technician	Ongoing

Review Date

Name: F. Burke Signature/s. F. Burke. Date: 3/4/17

Name: K. Petty Signature/s....*X Petty*...... Date: 15/6/20

Name: G. Cruickshank Signature/s G. Cruickshank Date: 20.06.22